Installation Instructions

Pre-Instalaltion

Pre-installation:

Inspect material to verify all material has been received.

Report shipping damage or missing items immmediately.


Organize all material by 'System' using BOM per System.

inter•lux

components supplied with housings

820-10220-101 Straight connector w/ 4 x M4 set screws








Installation Instructions

inter•lux

Systems - Straight Runs 'S'




'S', with End Returns

Installation Instructions

inter•lux


Systems - Patterns 'P2C' and 'P2R



Installation Instructions

inter•lux


Systems - Patterns P3C' and 'P3R'



Installation Instructions

inter•lux


Systems - Patterns 'P4C' and 'P4R'



Installation Instructions


Rough-in


inter-lux





Installation Instructions

Mounting Housing









Housing Installation:

 Mount housing onto finished mounting surface (cove wall) with #8 pan head screws at 16" on center using continuous screw port located in housing.

Pre-drilling pilot hole to align with structure is recommended to simplify mounting.

inter-lux

Recommend starting at end of straight runs or at the corner for patterns.

2. Screws shall fasten to wall/ceiling building framing members. Total fixture weight 1.5 lbs per foot.

Increase weight as required to accomodate light fixtures supplied by others.

- 3. Mount additional housings as indicated in #3 above with the addition of sliding the pre-installed joint connector and nose alignment connector to attach joining extrusions.
- 4. Secure connectors in place with four set screws (two set screws on each side of the joint).
- 5. Install all housings within a given 'System' repeating #1 and #2 above.
- Install 5/8" drywall to the underside of the housing and fasten with 1 1/4" drywall screw 1 7/8" from housing nose edge.
- 7. Apply drywall mud and mesh tape to form a smooth taper from housing nose edge to ajoining ceiling plan or wall surface. Apply multiple thin coats of mud to ensure a smooth taper. Allow each coat to dry and sand smooth before applying the next coat of mud.
- 8. Apply paint primer and paint color.

Important:

Housing lengths are based on finished mounting surface dimensions as approved on submittal drawings. Any deviation in the finished mounting surface dimension will result in housings being too long or too short. If this occurs new housings will need to be ordered with the exact length required to complete the 'System(s)'.

whitegoods

Drywall Mud Skim Coat