Surface

Surface Mount

Installation Instructions

Luminaires must be installed by a qualified electrician. Check with local and national codes for proper installation.




To prevent electrical shock disconnect electrical supply before installation or servicing.

Never connect a live fixture!!!

Contractor is responsible for adequately reinforcing walls and/or ceilings to support fixture weight. Provide blocking when necessary.

Step 1 - Open the Box







Surface


Surface Mount

Installation Instructions

Page 2 of 10

Step 2 - Ceiling Prep - All Mounts

- Mark position of fixture (stand-alone unit or multiple units) on ceiling.
- **b** Mark position of hole for Power Feed




Step 3 - Install Joiners and End Caps


If installing a **Stand-Alone fixure, skip to Step 4**. End Caps come installed at factory.

For an *Multi Unit Run*, use Joiner Kit (Joiner plus four Set Screws) for every two units, and continue below.

a Insert Joiner halfway into back channel of Unit A. Tighten two Set Screws to secure. Do not overtighten.



Insert Joiner/Unit A into Unit B. Draw together and tighten two Set Screws to secure. Do not overtighten.



whitegoods

Installation Instructions

Surface

Surface Mount


Page 3 of 10

Step 3 - Continued

c Install Endcap on first and last units of run. Secure each with supplied screw.

Endcaps illustrated at far right install the same way with supplied screw.

See Page 10 for Diffusers compatible with these Endcaps





End Cap for Round Opal Difffuser



End Cap for Narrow Lens, 16°

Step 4 - Mounting Options

Screw Clip

Bolt Slot Tegular Clip

T-Bar Grid Clip


Magnet Mount


Tegular Grid Clip


Adjustable Bracket

Screw Clip (SC)

If fixture is to be installed on a hard ceiling, unit will come with Screw Clips that are screwed directly to the surface. Clip snaps into channel opposite the diffuser. Screws or anchors supplied by others.











Surface

Surface Mount


Page 4 of 10

Installation Instructions

Step 4 - Continued


T-Bar Grid Clip (GT9/GT15)


a Luminaire unit comes with clips for mounting to a suspended ceiling grid. Minimum (2) brackets per fixture, maximum offset 36" on center. Orient Clip as shown on next page.



Place clip on T-Bar at an angle, then rotate clip counter-clockwise. Mounting tabs will slide over flat surfaces of Tee just below ceiling tile. Repeat as necessary.

Space clips evenly.









Surface

Surface Mount


Page 5 of 10

Installation Instructions


Step 4 - Continued

Marking and Drilling Power Feed Hole (for T-Bar Grid Clip)

- a Mark location of exiting power feed on a non-visible area of Tee. Hole should be at least 2.5" from corner.
- b Locate supplied drilling jig.



The drilling jig's magnets cling to both sides of the vertical element of the Tee. Each side of the horizontal element slips into the pocket (see illustrations above and below) on either end of jig with the same twisting motion of the Grid Clip.







Surface


Surface Mount

Page 6 of 10

Installation Instructions

Step 4 - Continued

b Use large hole (FEED) in drilling jig and line up jig with mark. Note that hole in jig is slightly off center. Drilled hole may be shifted left or right of center depending on orientation of jig. Orient jig as needed.








Surface


Surface Mount


Page 7 of 10


Installation Instructions


9/16" Bolt Slot Tegular Clip (BS9T)











Push Fixture onto Clip





Surface


Surface Mount


Installation Instructions

Page 8 of 10

Tegular Grid Clip (GT9T)


Installation for the Tegular Grid Clip follows that of regular T-Bar Grid Clips. The difference is only a matter of height, allowing this clip to sit recessed within the ceiling tiles.






Magnet Mount (MM)

To mount to steel surface, the magnet mount can be used. Minimum (2) magnets per fixture, maximum offset 24" on center.










Surface

Surface Mount

Installation Instructions

Page 9 of 10



Step 5 - Mounting

Gently push luminaire onto clips, or onto ferrous metal surface, in the case of magnet mounts.

Step 6 - Wiring

Gently push luminaire up onto clips, or onto ferrous metal surface, in the case of magnet mounts.





20 Linear


WG-20LDL-


Lens Options


Surface


Page 10 of 10


Surface Mount











Round Opal Diffuser (ROD)



