2.4" ProTools

WG-60RPTDLID-SM

J-Box (by others)

Cross Bar-

Cross Bar

Screw (2)

Canopy

Plate

Rim

Set

Screw

Fixture

Body

whitegoods

Mounting

Mounting

Screw (2)

Installation Instructions

Downlight

Round Cylinder Tall Surface Mount

IMPORTANT: Fixture(s) must be wired in series! Refer to driver wiring document

Luminaires must be installed by a qualified electrician. Check with local and national codes for proper installation.



To prevent electrical shock disconnect electrical supply before installation or servicing

Never connect a live fixture!!!

Contractor is responsible for adequately reinforcing walls and/or ceilings to support fixture weight. Provide blocking when necessary.

Integral Driver

Step 1 Open the Box

Unpack luminaire unit.

Step 2 **Ceiling Preparation**

Mark location, cut opening, and mount J-Box. Pull power (and control) cable(s) inside. Mount Cross Bar using supplied screws.

Step 3 **Electrical Connection**

- From Fixture, feed cable through Mounting Plate, followed by Canopy.
- Inside J-Box, connect power (and control) wire(s) using suitable connectors.


Step 4 Mount Luminaire

- Secure Canopy and Mounting Plate to J-Box using supplied Mounting Screws.
- **b** Slip Fixture Body over Rim of Mounting Plate. Secure by rotating clockwise. Lock into place with Set Screw. Energize!



Included in Box

- (1) Fixture Body with Integral Driver & connected cable
- (1) Cross Bar
- (2) Cross Bar Screws
- (1) Mounting Plate
- (1) Canopy
- (2) Mounting Screws
- (1) Set Screw



Cross-Section of Fixture

